MODEL NO .: SCK DIRECT II **DATE: 1120**

RoHS FCC ID: UJ7-XWIRE-DIRECT

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interferance, and (2) this device must accept any interferance received, including interferance that may cause undesired operation.

MAC: 0016DE010000067F Manufactured By

OD AUTOMATION - SERVICE TECHNIQUES, INC.

905 Honeyspot Road, Stratford, CT 06615 USA The products manufactured by FAST are protected under one or more of the following U.S. Patents: 5,331,575 5,539,671 5,711,606 5,723,846 5,726,424 5,875,430 6,142,666 6,339,930 6,401,467 6,505,546 6,581,391 7,015,433 7,650,833 Plus foreign patents and patents pending. Plus licensed patent 5,973,297.

©2011 Food Automation - Service Techniques, Inc., (FAST.)® The computer program contained herein is the property of FAST and may not be copied in whole or in part without prior written authorization from FAST Disassembly by unauthorized service agency will void warranty.

1-800-243-9271

00V08311001



SCK® Use of the communication port is subject to the terms of a End User License Agreement. All other use is strictly unauthorized and is strictly prohibited.



Food Automation - Service Techniques Stratford, CT., USA

RoHS

The products manufactured by FAST are protected under one or more of the following U.S. Patents: 5,331,575 5,539,671 5,711,606 5,723,846 5,726,424 5,875,430 6,142,666 6,339,930 6,401,467 6,581,391 7,015,433 7,650,833

Plus foreign patents and patents pending. Plus licensed patent 5,973,297.

②2011 Food Automation - Service Techniques, Inc., (FAST.)® The computer program contained herein is the property of FAST and may not De copied in whole or in part without prior we