Christoph Schmidt

Von: Generic Office of Engineering Technology [oetech@fccsun27w.fcc.gov]

Gesendet: Mittwoch, 13. Dezember 2006 17:24

An: c.schmidt@emcc.de

Betreff: Response to Inquiry to FCC (Tracking Number 895192)

Inquiry:

TCB request for guidance.

TCB Ref.: intended FCC ID: UJDFM88

b) FCC Rule part: 15.239

c) FM Transmitter for operation inside a car, according to permit but ask list 1). Equipment Class: DXX

d) The device has been tested for compliance with all provisions of Rule part 15.239, using the test procedures described in ANSI C63.4 - 2003 as appropriate. The device was tested in an anechoic chamber and was not tested inside a car.

---Reply from Customer on 12/12/2006---

Follow up inquiry: TC#: 787031 FCC ID: UJDFM88 Q & A and Test Report: please refer to attachments. Form 731 and all exhibits have been uploaded for FCC review.

---Reply from Customer on 12/12/2006---

We received the following information from our client / test lab: Dear Mr. Schmidt, The FM transmitter, UJDFM88, has been additionally tested / verified and it does work in a typical car. Best regards, Wang Wei

Response:

Go ahead and grant. No need for further replies. Please submit a copy of this inquiry into the filing. Thanks.

Do not reply to this message. Please select the <u>Reply to an Inquiry Response</u> link from the OET Inquiry System to add any additional information pertaining to this inquiry.