Test report No. : 10706993H-A-R1
Page : 38 of 38
Issued date : June 3, 2015
Revised date : June 5, 2015
FCC ID : UJHNR000

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission




Photo 1




Photo 2

End of Report

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124