Test report No. : 10512882H-A-R1

Page : 34 of 34

Issued date : December 11, 2014
Revised date : March 9, 2015
FCC ID : UJHBD1G

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission




Photo 1




Photo 2

End of Report

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124