Test report No. : 10792621H
Page : 47 of 47
Issued date : July 13, 2015
FCC ID : UJHAR0H

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission



Photo 1




Photo 2

End of Report

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124