Test report No. : 12608632H-B-R1
Page : 49 of 49
Issued date : May 22, 2019
FCC ID : UJHR1LOW

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission




Photo 1



Photo 2

End of Report

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124