Test report No. : 10521972H-A
Page : 49 of 50
Issued date : December 9, 2014
FCC ID : UJHNTG5HUE213

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission




Photo 1




Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124


Test report No. : 10521972H-A
Page : 50 of 50
Issued date : December 9, 2014
FCC ID : UJHNTG5HUE213

Worst Case Position (Horizontal: Z-axis/ Vertical: Y-axis)


X-axis



Y-axis



Z-axis



End of Report

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124