Test report No. : 10607274H-B
Page : 51 of 52
Issued date : June 26, 2015
FCC ID : UJHNR213

# **APPENDIX 3: Photographs of test setup**

# **Radiated Spurious Emission**




Photo 1




Photo 2

## UL Japan, Inc. Ise EMC Lab.


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124


Test report No. : 10607274H-B
Page : 52 of 52
Issued date : June 26, 2015
FCC ID : UJHNR213

# Worst Case Position (Horizontal: X-axis/ Vertical: Y-axis)


### X-axis



Y-axis



**Z**-axis



**End of Report** 

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124