Test report No. : 11394939H-B-R1 Page : 49 of 50

Issued date : October 25, 2016 FCC ID : UJHNTG55HUE

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission




Photo 1




Photo 2

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124


Test report No. : 11394939H-B-R1 Page : 50 of 50

Issued date : October 25, 2016 FCC ID : UJHNTG55HUE


Worst Case Position

(Above 1GHz: Horizontal: X-axis/ Vertical: Y-axis) (Below 1GHz: Horizontal: Y-axis/ Vertical: Y-axis)


X-axis



Y-axis



Z-axis



End of Report

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124