Test report No. : 10184498H-A-R2
Page : 51 of 52
Issued date : June 19, 2014
Revised date : June 23, 2014
FCC ID : UJHNR244245BTWL

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission Model No. NR-244UH



Photo 1




Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 10184498H-A-R2
Page : 52 of 52
Issued date : June 19, 2014
Revised date : June 23, 2014
FCC ID : UJHNR244245BTWL

Radiated Spurious Emission Model No. NR-245UH



Photo 1




Photo 2

End of Report

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124