Test report No. : 11394939H-A-R1 Page : 41 of 42

Issued date : October 25, 2016 FCC ID : UJHNTG55HUE

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission




Photo 1




Photo 2

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124


Test report No. : 11394939H-A-R1
Page : 42 of 42
Issued date : October 25, 2016
FCC ID : UJHNTG55HUE

Worst Case Position

(Above 1GHz: Horizontal: Z-axis/ Vertical: Y-axis) (Below 1GHz: Horizontal: Y-axis/ Vertical: Y-axis)







End of Report

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124