Test report No. : 10012781H-A
Page : 68 of 73
Issued date : July 24, 2013
FCC ID : UJHNR241NR243

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission (NR-241 (Left handle))




Photo 1




Photo 2

UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Test report No. : 10012781H-A
Page : 69 of 73
Issued date : July 24, 2013
FCC ID : UJHNR241NR243

Radiated Spurious Emission (NR-241 (Right handle))




Photo 1



Photo 2

UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Test report No. : 10012781H-A
Page : 70 of 73
Issued date : July 24, 2013
FCC ID : UJHNR241NR243

<u>Radiated Spurious Emission</u> (NR-243UH (Internal Amplifier))




Photo 1



Photo 2

UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Test report No. : 10012781H-A
Page : 71 of 73
Issued date : July 24, 2013
FCC ID : UJHNR241NR243

<u>Radiated Spurious Emission</u> (NR-241UH (Internal Amplifier))




Photo 1




Photo 2

UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Test report No. : 10012781H-A
Page : 72 of 73
Issued date : July 24, 2013
FCC ID : UJHNR241NR243

<u>Radiated Spurious Emission</u> (NR-241UH (External Amplifier))




Photo 1



Photo 2

UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Test report No. : 10012781H-A
Page : 73 of 73
Issued date : July 24, 2013
FCC ID : UJHNR241NR243

<u>Radiated Spurious Emission</u> (NR-243UH (External Amplifier))




Photo 1



Photo 2

End of Report

UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN