Test report No. : 11830772H-A-R1 Page : 41 of 41

Issued date : November 29, 2017

FCC ID : UJHSU0G

## **APPENDIX 3: Photographs of test setup**

## **Radiated Spurious Emission**




Photo 1




Photo 2

## **End of Report**

## UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124