Test report No. : 11577935H-A
Page : 45 of 45
Issued date : February 28, 2017
FCC ID : UJHAR0M

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission




Photo 1




Photo 2

End of Report

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124