
Test report No. : 28JE0209-HO-01-A
Page : 17 of 44
Issued date : October 28, 2008
FCC ID : UJHNR21263AF39508

APPENDIX 1: Photographs of test setup

Spurious Emission (Radiated)





UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124


 Test report No.
 : 28JE0209-HO-01-A

 Page
 : 18 of 44


 Issued date
 : October 28, 2008

 FCC ID
 : UJHNR21263AF39508

Antenna Worst Case Position (Horizontal: X-axis/ Vertical: Y-axis)







UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124