Test report No. : 10762685H-R1
Page : 47 of 47
Issued date : May 13, 2015
Revised date : June 30, 2015
FCC ID : UJHRV1M

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission



Photo 1




Photo 2

End of Report

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124