Test report No. : 10607274H-A-R1
Page : 44 of 45
Issued date : June 26, 2015
Revised date : July 7, 2015
FCC ID : UJHNR213

## **APPENDIX 3: Photographs of test setup**

## **Radiated Spurious Emission**




Photo 1




Photo 2

## UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124


Test report No. : 10607274H-A-R1
Page : 45 of 45
Issued date : June 26, 2015
Revised date : July 7, 2015
FCC ID : UJHNR213

Worst Case Position
2.4GHz: (Horizontal: Z-axis/ Vertical: X-axis)

X-axis



Y-axis



**End of Report** 

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124