Appendix C. Set up Photograph

Conducted Emission

Mode 1



FRONT VIEW




REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC ID: UJU9QSTEAL000 Page No. : C1 of C5
Report Issued Date : Jun. 27, 2007
Report Version : Rev. 01


Report No.: FR760116-01





SIDE VIEW


Mode 2



FRONT VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC ID: UJU9QSTEAL000 Page No. : C2 of C5
Report Issued Date : Jun. 27, 2007
Report Version : Rev. 01





REAR VIEW



SIDE VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC ID: UJU9QSTEAL000 Page No. : C3 of C5
Report Issued Date : Jun. 27, 2007
Report Version : Rev. 01



Radiation Emission

Mode 1-6



FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC ID: UJU9QSTEAL000 Page No. : C4 of C5
Report Issued Date : Jun. 27, 2007
Report Version : Rev. 01





Mode 7-9



FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC ID: UJU9QSTEAL000 Page No. : C5 of C5
Report Issued Date : Jun. 27, 2007
Report Version : Rev. 01