9. SETUP PHOTOS

RADIATED MEASUREMENT SETUP





TEL: (510) 771-1000 This report shall not be reproduced except in full, without the written approval of UL CCS.

TEMPERATURE CHAMBER MEASUREMENT SETUP



LINE CONDUCTED EMISSIONS SETUP





END OF REPORT