January 29, 2007

Receptors International Security Group 103 Barrows Way Folsom, CA 95630

c/o: Flom Test Lab

Attention: Jackie Pillai

We have reviewed the application for certification authorization which was submitted to Elite.

Upon review of your application it was determined that additional information is required to complete the application for certification authorization. The additional information required is listed below:

## Administrative Review:

- 1. The External Photos show the FCC ID as UKS R100PR125. Spaces are not allowed in FCC ID numbers. The FCC ID Label exhibit shows the FCC ID as UKS-R100PR125. The application (CSF-20-03) lists the FCC ID as UKSR100PR125.
- 2. The application for Industry Canada is not complete. An email address is required for Canadian representative. 99% bandwidth is required. Emission designator is required.
- 3. The frequency range listed on the TCB application is incorrect.

The application for certification authorization cannot continue until all information requested above is returned to Elite.

The status of your application for certification authorization has been placed on hold for a period of 30 days. During this time Elite will be happy to answer any questions or assist in any way possible for a successful grant of certification authorization. At the conclusion of the allotted 30 day period, Elite reserves the right to dismiss your application for certification authorization if no reply to this inquiry is received.

Sincerely,

Daniel E. Crowder Certification Department Supervisor ELITE ELECTRONIC ENGINEERING