MOBILETRON ELECTRONICS CO.,LTD., FCC ID: ULZ-TX014, Assessment NO.: AN07T7108, Notice#1 Inbox

from "vicky.liu" <vicky.liu@tw.ccsemc.com>

hide details 2:37 am (5 hours ago) A Reply



to tim.dwyer@ccsemc.com

cc application@tw.ccsemc.com

date Aug 15, 2007 2:37 AM

subject MOBILETRON ELECTRONICS CO.,LTD., FCC ID: ULZ-TX014, Assessment NO.: AN07T7108, Notice#1

Dear Tim,

Thank you for your reply and my answer is as belowing.

Q1: Please provide internal photos with the black heat-shrink material removed so that the antenna is showing.

Ans: Please find the attachment for internal photo.

Vicky Liu 劉淑芳

Certification Dept.



Compliance Certification Services Inc.

Rm.258, Bldg.17, No.195, Sec.4, Chung Hsing Rd., Chutung, Hsinchu, Taiwan, R.O.C.

Tel: 886-3-5910068 EXT: 504

Fax: 886-3-5825720

E-mail: vicky.liu@tw.ccsemc.com URL: http://www.ccsemc.com.tw



----- 轉呈者 vicky.liu/ccsemc 於 2007/08/15 09:35 AM -----

<tim.dwyer@ccsemc.com>

收件人: "Vicki Liu" <application@tw.ccsemc.com>

副本抄送: <tim.dwyer@ccsemc.com> 2007/08/15 09:22 AM

主旨: MOBILETRON ELECTRONICS CO.,LTD., FCC ID: ULZ-TX014, Assessment NO.: AN07T7108, Notice#1

Dear Vicki,

The application review is complete. All technical issues are ok, but there is one administrative issue as shown below.

Q1: Please provide internal photos with the black heat-shrink material removed so that the antenna is showing.

Best regards,

Tim Dwyer

CCS Technical Reviewer

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

This e-mail transmission is confidential and intended solely for being reviewed by the recipient(s) identified above. If you are not an identified recipient, please ensure that this communication remains confidential and promptly return it to the sender. Please contact immediately by phone (Tel: 886-2-2299-9720) for any problem with this transmission. Thank you for your attention.



TX014_Internal Photo(960815).pdf

93K View as HTML Download