

February 27, 2007

FCC

Subject: FCC ID UMUS751433LR4

Gentlemen:

The test report originally submitted with this application was found to have an error on page 20 regarding the factors reported as used to correct the measurement of one of the spurious measurements from the receiver reading in dBuV to a field strength in dBuV/m. The corrected amplitude in dBuV/m that was compared to the limit was calculated using the correct values. It was only a typographical error in the factors listed in the report. A revised test report has been uploaded.

Sincerely,

David W. Bare

CTO

Elliott Laboratories Inc.

Havedw Bare