

Test report No. : 27AE0132-HO-A
Page : 9 of 15
Issued date : October 25, 2006
FCC ID : UNK-FW01

# **APPENDIX 1: Photographs of test setup**

# **Radiated emission**

#### \_ .





### UL Apex Co., Ltd. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124

Test report No. : 27AE0132-HO-A
Page : 10 of 15
Issued date : October 25, 2006

FCC ID : UNK-FW01

# Worst case position (Horizontal: X-axis/Vertical: Y-axis)







### UL Apex Co., Ltd. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124