Helen Zhao

----Original Message-----

From: amanda.wu [mailto:amanda.wu@tw.ccsemc.com]On Behalf Of application

Sent: Friday, October 20, 2006 4:01 AM

To: Helen Zhao

Subject: Re:FW: TELEWELL ELECTRIC CO.,LTD., FCC ID: UNLBTP33, Assessment NO.: AN06T6230, Notice#1

Dear Helen:

Please see my reply, thank you.

Best Regards,

Amanda

----Original Message-----From: Helen Zhao

Sent: Monday, October 16, 2006 5:29 PM

To: Helen Zhao

Subject: TELEWELL ELECTRIC CO., LTD., FCC ID: UNLBTP33, Assessment NO.:

AN06T6230, Notice#1

Question #1: The operational description of the Bluetooth chip shows the device has the capability to transmit in one time slot, three time slots and 5 time slots, but the test report provides Dwell time test data at DH1 mode only. Please provide test data at DH3 and DH5.

Ans: The operational description had been revised .(Please see page 9)

Question #2: Appendix - RF exposure in the test report indicates SAR evaluation is applied, "Please refer to the separate SAR report". Please explain where is the SAR report, why this device needs SAR evaluation.

Ans: As per client's required to test SARevaluation. Please see the attachment.

Best Regards, Helen Zhao

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.