
Page : 12 of 40

Revised date : November 21, 2006
Revised date : December 5, 2006
FCC ID : UOEME-M21

APPENDIX 1: Photographs of test setup

Conducted emission(ME-MR21-A-SG)





Side



UL Apex Co., Ltd. Head Office EMC Lab.


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Page : 13 of 40


Revised date : November 21, 2006
Revised date : December 5, 2006
FCC ID : UOEME-M21

Conducted emission (ME-MA21-A-SNT)

Front



Rear




UL Apex Co., Ltd. Head Office EMC Lab.


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Page : 14 of 40

Revised date : November 21, 2006
Revised date : December 5, 2006
FCC ID : UOEME-M21

Radiated emission (ME-MR21-A-SG)





UL Apex Co., Ltd. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

: 15 of 40 Page


Issued date : November 21, 2006 : December 5, 2006 Revised date FCC ID : UOEME-M21

Worst Case Position (ME-MR21-A-SG) (Z-axis)





Y-axis



Z-axis



UL Apex Co., Ltd. **Head Office EMC Lab.**


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


: +81 596 24 8116 Telephone Facsimile : +81 596 24 8124

Page : 16 of 40

Revised date : November 21, 2006
Revised date : December 5, 2006
FCC ID : UOEME-M21

Radiated emission (ME-MA21-A-SNT)





UL Apex Co., Ltd. Head Office EMC Lab.


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Page : 17 of 40

Revised date : November 21, 2006
Revised date : December 5, 2006
FCC ID : UOEME-M21

Worst Case Position (ME-MA21-A-SNT) (Z-axis)







UL Apex Co., Ltd. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN