Test report No. : 10131696H-A-R1 Page : 23 of 26

Issued date : December 20, 2013
Revised date : December 25, 2013
FCC ID : UOEME-M26U

APPENDIX 3: Photographs of test setup

Conducted emission



Photo 1




Photo 2

UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Test report No. : 10131696H-A-R1 Page : 24 of 26

Issued date : December 20, 2013
Revised date : December 25, 2013
FCC ID : UOEME-M26U

Radiated emission



Photo 1




Photo 2

UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Test report No. : 10131696H-A-R1 Page : 25 of 26

Issued date : December 20, 2013 Revised date : December 25, 2013 FCC ID : UOEME-M26U

Worst Case Position

Below 30MHz Antenna: Z-axis / Module: X-axis

Above 30MHz Antenna (Horizontal: X-axis / Vertical: X-axis) Module (Horizontal: X-axis / Vertical: X-axis)




UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Test report No. : 10131696H-A-R1 Page : 26 of 26

Issued date : December 20, 2013
Revised date : December 25, 2013
FCC ID : UOEME-M26U

With/Without Tag



With Tag



Without Tag (Worst)

End of Report

UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN