Test report No. : 10904156H-A-R2
Page : 22 of 25
Issued date : August 17, 2015
Revised date : August 27, 2015
FCC ID : UOEME-M23B

# **APPENDIX 3: Photographs of test setup**

# **Conducted emission**




Photo 1




Photo 2

# UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Test report No. : 10904156H-A-R2

Page : 23 of 25

Issued date : August 17, 2015
Revised date : August 27, 2015
FCC ID : UOEME-M23B

# **Radiated emission**



Photo 1




Photo 2

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Test report No. : 10904156H-A-R2
Page : 24 of 25
Issued date : August 17, 2015
Revised date : August 27, 2015
FCC ID : UOEME-M23B

## **Worst Case Position**

#### Antenna

Below 30MHz Y-axis (without Tag)

**Above 30MHz** Horizontal: X-axis / Vertical: X-axis (with Tag)

#### Module

Below 30MHz X-axis

**Above 30MHz** Horizontal: X-axis / Vertical: X-axis

## Antenna X-axis



Module X-axis



Y-axis




Y-axis



**Z**-axis



**Z**-axis



UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Test report No. : 10904156H-A-R2
Page : 25 of 25
Issued date : August 17, 2015

Revised date : August 27, 2015 FCC ID : UOEME-M23B

# With/Without Tag

With Tag (Above 30 MHz; worst)





**End of Report** 

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN