Page
 : 14 of 48

 Issued date
 : March 1, 2010

 Revised date
 : July 23, 2010

 FCC ID
 : UOE-0015573942

APPENDIX 1: Photographs of test setup

Conducted emission 4ch type



Photo 1




Photo 2

UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

 Page
 : 15 of 48

 Issued date
 : March 1, 2010

 Revised date
 : July 23, 2010

 FCC ID
 : UOE-0015573942

Conducted emission 8ch type




Photo 1




Photo 2

UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

 Page
 : 16 of 48

 Issued date
 : March 1, 2010

 Revised date
 : July 23, 2010

 FCC ID
 : UOE-0015573942

Radiated emission 4ch type



Photo 1




Photo 2

UL Japan, Inc.

Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

 Page
 : 17 of 48

 Issued date
 : March 1, 2010

 Revised date
 : July 23, 2010

 FCC ID
 : UOE-0015573942

Radiated emission 8ch type




Photo 1




Photo 2

UL Japan, Inc.

Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Page : 18 of 48

Issued date : March 1, 2010

Revised date : July 23, 2010

FCC ID : UOE-0015573942

Worst Case Position


Below 30MHz Z-axis

Above 30MHz Horizontal: Z-axis / Vertical: Z-axis

Module X-axis







UL Japan, Inc.

Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Page : 19 of 48

Issued date : March 1, 2010

Revised date : July 23, 2010


FCC ID : UOE-0015573942

Worst Case Position

Below 30MHz Y-axis

Above 30MHz Horizontal: Y-axis / Vertical: Y-axis

Antenna V avis



Y-axis



Z-axis



UL Japan, Inc.

Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


: 30FE0017-HO-01-A-R2 Test report No.

Page : 20 of 48 **Issued date** : March 1, 2010 Revised date FCC ID : July 23, 2010 : UOE-0015573942

Worst Case Position







4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 : +81 596 24 8124 Facsimile