Test report No. : 31GE0106-HO-02-A-R1

Page : 13 of 27
Issued date : March 29, 2011
Revised date : March 31, 2011
FCC ID : UOEME-K01

APPENDIX 1: Photographs of test setup

Conducted emission



Photo 1




Photo 2

UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124

Test report No. : 31GE0106-HO-02-A-R1

Page : 14 of 27
Issued date : March 29, 2011
Revised date : March 31, 2011
FCC ID : UOEME-K01

Radiated emission



Photo 1




Photo 2

UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124

Test report No. : 31GE0106-HO-02-A-R1

Page : 15 of 27
Issued date : March 29, 2011
Revised date : March 31, 2011
FCC ID : UOEME-K01

Worst Case Position



With Tag



Without Tag

UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124