



Ref: US.000266

29th April 2009

To FCC

BABT
Balfour House, Churchfield Road
Walton on Thames
Surrey, KT12 4TD
United Kingdom
Telephone: +44 (0)1932 251200
Fax: +44 (0)1932 251201

Direct Dial: +44 (0)1932 251230 E-mail: Tom.Twynam@babt.com Website: www.babt.com

Evaluation of Inventec CM-G100 FCC id: UPMJGW200001

I have assessed the above referenced submission for Inventec Appliances (Jiangning) Corporation and found it to be compliant. The product is a GSM/GPRS 1900 Module.

The following points were noted and resolved during the evaluation.

1. Module Characteristics

The letter confirming compliance with the FCC requirements for modules was not formalised. A revised signed document on company letterhead paper was received to correct this.

2. Test Reports

The test reports which were originally supplied had an incorrect registration number for FCC. The reports were subsequently issued with the new registration number for the State Monitoring Centre.

3. User Manual

There was no information regarding the installation requirements and antenna details or information regarding the visibility of the FCC ID label when installed in a host. Amendments were made to the manual and re-submitted.

Yours sincerely

Tom Twynam Technical Certifier For BABT TCB

J. J. Twynam