

FCC TEST REPORT REPORT NO.: FR020304

APPENDIX B. Photographs of EUT






PAGE NUMBER: B1 OF B5


: UQL-RC2-SC4404R

SPORTON International Inc.

TEL: 886-2-2696-2468 FCC ID FAX: 886-2-2696-2255

FCC TEST REPORT





SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 PAGE NUMBER : B2 OF B5

FCC TEST REPORT REPORT NO.: FR020304







SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 PAGE NUMBER : B3 OF B5

FCC TEST REPORT No.: FR020304





SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 PAGE NUMBER : B4 OF B5

FCC TEST REPORT



TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 PAGE NUMBER : B5 OF B5