

FCC TEST REPORT


APPENDIX B. Photographs of EUT






TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 PAGE NUMBER : B1 OF B4


FCC TEST REPORT REPORT NO.: FR040732






TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 PAGE NUMBER : B2 OF B4

FCC TEST REPORT REPORT NO.: FR040732






SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 PAGE NUMBER : B3 OF B4

FCC TEST REPORT NO.: FR040732





TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 PAGE NUMBER : B4 OF B4