

Valeo Raytheon Systems, Inc. 46 River Road Hudson, NH 03051 USA

Document No.:

VRS-100500

Date:

13 February 2007

To: Whom It May Concern

Subject: TCB labeling requirements for FCC ID: UR8100206

This letter is in response to the TCB comment, shown below, regarding labeling information.

"LABEL SAMPLE: Please have the applicant add the two-part warning statement to the device. This device seems to be large enough for the statement to be placed on the device"

Adding the two-part warning statement to the existing label is not possible for the following reasons:

- 1. The label size is restricted to the current area so that the label remains visible after assembly to the vehicle mounting bracket.
- 2. The current label is sized to fit a target area that has been molded into the product housing. This target area ensures the label position so that it remains visible after installation into the mounting bracket.
- 3. The production line that has been validated to produce this product is not capable of printing the two-part warning statement onto the current label area. The resolution of the label printer will not allow for the small font size necessary to get all of the information on the existing label size.
- 4. The two-part warning statement is included in the VRS and OEM user manuals.
- 5. The product is not accessible to the user after installation of the product on the vehicle. It is located behind the rear plastic bumper.

Consideration in this matter is greatly appreciated.

Sincerely,

Stephen LeBlanc

Multi-Beam Radar Lead Engineer

Valeo Raytheon Systems, Inc.