

**Federal Communications Commission** 7345 Oakland Mills Road Columbia MD 21046

Attention: Application Examiner / Review Engineer

Subject: Request for a Change in Identification per Section §2.933 of the FCC Rules

Reference: FCC ID: URA-MS32018

## To the Commission:

This change in identification request applies for a new FCC ID as established in 47 CFR 2.933(b) for a currently approved device.

This application by Draeger Medical Systems, Inc. will establish a new FCC ID under Draeger Medical Systems, Inc grantee code for the purpose of marketing.

The original grant to Redpine Signals Inc. with FCC ID:XF6-RS9113DB will remain in effect.

An authorization letter by Redpine Signals Inc. is attached.

## Per 2.933(b)

- 1.) The original identification is: FCC ID:XF6-RS9113DB
- 2.) The original granted date is: 01/13/2015
- 3.) The equipment is electrically identical.
- 4.) The original test results are applicable and representative of this changed device
- 5.) External photographs incl. FCC ID label location info are included in this application.

The following files are electronically submitted as attachments:

Cover Letter

Draeger Medical Inc. / Draeger Medical Systems Inc. 6 Tech Drive 3135 Quarry Road Andover, MA 01810 Telford, PA 18969 USA Tel +1 215 721 5400

www.draeger.com

Draeger Medical Systems Inc. USA Tel +1 978 379 8000 www.draeger.com



- External Photos
- ID Label and Location Info

Sincerely

Draeger Medical Systems, Inc

Georgios Kokovidis

Lead Wireless Engineer, Manager Wireless Solutions Group

Research and Development

Date: 18 December 2015