

Certification and Engineering Bureau **Industry Canada** 3701 Carling Avenue (Building 94) P.O. Box 11490, Station "H" Ottawa, Ontario K2H 8S2

January 11, 2016

Attention: Application Examiner / Review Engineer

Subject: Cover Letter for Change in ID application

The Change in ID for

IC: 5895B-MS32018

Model: DRAEGER WCM9113 802.11 ABGN V2

covers the frequency bands

2402 to 2480 MHz 2405 to 2480 MHz 2412 to 2462 MHz

5180 to 5220 MHz Not enabled 5745 to 5825 MHz Not enabled

During initialization of the wireless module a band of operation must be selected. The Dräger product software is hard coded to only enable the 2.4GHz band of operation, thus the 5GHz band of operation is disabled and cannot be configured by the product without a software change to the Dräger product.

Sincerely,

Draeger Medical Systems, Inc.

Beth Zis

**Director of Regulatory Affairs** 

Draeger Medical Inc. / Draeger Medical Systems Inc. 6 Tech Drive 3135 Quarry Road Telford, PA 18969

Tel +1 215 721 5400 www.draeger.com

Draeger Medical Systems Inc.

Andover, MA 01810

USA

Tel +1 978 379 8000 www.draeger.com