
Project: 06CA55823 Underwriters Laboratories, Inc. Issued: 11/15/06
File: MC15465 Test Setup Photos Page 1 of 3
Test Report: 060112

Worst Case EUT Arrangement (Upright):

Radiated Emissions - FCC Part 15.249



Project: 06CA55823 Underwriters Laboratories, Inc. Issued: 11/15/06 File: MC15465 Test Setup Photos Page 2 of 3

Test Report: 060112

Worst Case Emissions - Test Set-Up Photo - Front:

Radiated Emissions - FCC Part 15.249



Note: EUT is placed on top of a piece of foam approximately 3 inches high. This was used to reduce unwanted effects (reflections) from wood surface at high frequencies. It also aids in positioning the device.

Project: 06CA55823 Underwriters Laboratories, Inc. Issued: 11/15/06
File: MC15465 Test Setup Photos Page 3 of 3
Test Report: 060112

<u>Test 1, Item A – Worst Case Emissions - Test Set-Up Photo - Rear:</u>

Radiated Emissions - FCC Part 15.249

