Client: HandEra, Inc.
Model: WF10020
Standards: FCC 15.247
FCC ID: URZ-WF10020
Report #: 2007132


Appendix M: Internal Photographs




Photograph 21: Hard Drive in Back Case




Photograph 22: Hard Drive Top




Photograph 23: Hard Drive Bottom




Photograph 24: PCB Back In Front Case




Photograph 25: PCB Front




Photograph 26: PCB Front with Bluetooth Shield removed




Photograph 27: PCB Back




Photograph 28: PCB Back with 802.11b Radio Removed



Photograph 29: Keypad PCB Back



Photograph 30: Side Button PCB Front




Photograph 31: Side Button PCB Back




Photograph 32: Keypad Front

Client: HandEra, Inc.
Model: WF10020
Standards: FCC 15.247
FCC ID: URZ-WF10020
Report #: 2007132



Photograph 33: Keypad PCB Front



Photograph 34: Keypad Back