Rhein Tech Laboratories, Inc. 360 Herndon Parkway Suite 1400 Herndon, VA 20170 http://www.rheintech.com Client: HandEra, Inc. Model #: PHRPAD40 Standard: FCC 15.247 FCC ID: URZ-WF10030 Report #: 2012195

Appendix K: Internal Photographs


Please refer to the following pages.



Location of chassis within unit



Location of 2400-00273, 2400-00284, 2400-00291, 2400-00306, 2400-00307, and 2400-00309 PCB assemblies on chassis.



Front and Rear of 2400-00306 PCB assembly



Front and Rear of 2400-00307 PCB assembly



Front and Rear of 2400-00309 flexible circuit board assembly




Front of 2400-00284 WiFi PCB assembly, without RF shield can




Front of 2400-00284 WiFi PCB assembly, with RF shield can




Rear of 2400-00284 WiFi PCB assembly, with RF shield can




Front of 2400-00273 PCB assembly




Rear of 2400-00273 PCB assembly




Rear of 2400-00273 PCB assembly with 2400-00284 radio PCBA installed




Front of 2400-00291 PCB assembly




Rear of 2400-00291 PCB assembly



Front of 2400-00319 PCB assembly



Rear of 2400-00319 PCB assembly



Location of 2400-00319 PCB assembly within Docking Cradle