Test report No. : 27DE0059-HO-A


Page : 9 of 18


Issued date : November 17, 2006 FCC ID : USA-AKS0620061

APPENDIX 1: Photographs of test setup

Conducted Emission







UL Apex Co., Ltd. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124


Test report No. : 27DE0059-HO-A

Page : 10 of 18

Issued date : November 17, 2006 FCC ID : USA-AKS0620061

Radiated Emission





UL Apex Co., Ltd. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124

Test report No. : 27DE0059-HO-A Page : 11 of 18

Issued date : November 17, 2006 FCC ID : USA-AKS0620061

Worst Case Position Below 30MHz X-axis Above 30MHz Hor: Y-axis, Ver: Y-axis

X-axis



Y-axis



Z-axis



UL Apex Co., Ltd. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124