



The manufacturer fixed a solder mounted bolt through out the male and female SMA connector of the antenna, so that the end user will not able to remove or replace the original antenna unless breaking and removing the bolt.