Test report No.
 : 26IE0294-HO-B-2

 Page
 : 9 of 22


 Issued date
 : July 10, 2006


 Revised date
 : January 25, 2007

 FCC ID
 : USTFMTMB02R3

APPENDIX 1: Photographs of test setup

Spurious Emissions






UL Apex Co., Ltd. Head Office EMC Lab.


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124

Test report No. : 26IE0294-HO-B-2
Page : 10 of 22
Issued date : July 10, 2006
Revised date : January 25, 2007
FCC ID : USTFMTMB02R3

Worst Case Position (Horizontal: Z-axis / Vertical: Y-axis)







UL Apex Co., Ltd. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124