12-3Fl, No. 27-1, Lane 169, Kang-Ning St., Hsi-Chih, Taipei Hsien, Taiwan, R. O. C.

TEL: 886-2-26922097 FAX: 886-2-26956236



NVLAP LAB CODE: 200097-0 REPORT NO. :E950418

FCC ID: UTBHLC830W

20. EUT Internal Photos

PHOTO. 3. EUT INSIDE VIEW



PHOTO. 4. EUT COMPONENT SIDE VIEW



12-3Fl, No. 27-1, Lane 169, Kang-Ning St., Hsi-Chih, Taipei Hsien, Taiwan, R. O. C.

TEL: 886-2-26922097 FAX: 886-2-26956236



NVLAP LAB CODE: 200097-0 REPORT NO. :E950418

FCC ID: UTBHLC830W




PHOTO. 6. EUT COMPONENT SIDE VIEW



12-3Fl, No. 27-1, Lane 169, Kang-Ning St., Hsi-Chih, Taipei Hsien, Taiwan, R. O. C.

TEL: 886-2-26922097 FAX: 886-2-26956236



NVLAP LAB CODE: 200097-0 REPORT NO. :E950418

FCC ID: UTBHLC830W

PHOTO. 7. EUT COMPONENT SIDE VIEW



PHOTO. 8. EUT SOLDERING SIDE VIEW



12-3Fl, No. 27-1, Lane 169, Kang-Ning St., Hsi-Chih, Taipei Hsien, Taiwan, R. O. C.

TEL: 886-2-26922097 FAX: 886-2-26956236



NVLAP LAB CODE: 200097-0 REPORT NO. :E950418

FCC ID: UTBHLC830W

PHOTO. 9. EUT COMPONENT SIDE VIEW



PHOTO. 10. EUT SOLDERING SIDE VIEW

