FE5500-TX Operational Description

This is a LCD display thermometer and humidity for house hold application.

The unit use 2 pcs of 1.5V battery in-series connection give 3V supply.

Devices operated under the provisions of this paragraph shall be provided with a means for automatically limiting operation so that the duration of each transmission shall be at least 30 times the duration of the transmission.

The function of the unit is to regularly measure its surrounding temperature and humidity at its point of location and transmit the data using wireless 433MHz to a standing alone receiving unit. The data would them be displayed on the receiving units LCD.

For all description please read the enclosed user instruction manual.