Test report No. : 27BE0182-HO-E-1

Page : 12 of 25


Issued date : December 14, 2006
Revised date : January 30, 2007
FCC ID : UUA-A09N

APPENDIX 1: Photographs of test setup

Conducted emission







UL Apex Co., Ltd. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124


: 27BE0182-HO-E-1 Test report No. : 13 of 25

Page

: December 14, 2006 : January 30, 2007 : UUA-A09N Issued date Revised date FCC ID

Radiated emission

Front



Rear





UL Apex Co., Ltd. **Head Office EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124

Test report No. : 27BE0182-HO-E-1
Page : 14 of 25
Issued date : December 14, 2006
Revised date : January 30, 2007
FCC ID : UUA-A09N





UL Apex Co., Ltd. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124