TÜV America Inc. 1775 Old Highway 8 NW Suite 104 New Brighton, MN 55112 Phone: (651) 631-2487 Fax: (651) 638-0285 E-mail: info@tuvam.com www.TUVamerica.com



04 September 2007

American TCB 6731 Whittier Avenue McLean VA 22101

RE: Wallace Technologies LLC

Response to 8-22-07 Comments

FCC ID: FCC ID: UUM10156V10 & IC: 6873A-10156V10

In response to your comments on the above submittal from 8-22-07.

1. ATCB Comments: The address on the FCC application form does not agree with the address in the FCC database. The address on the FCC database is: 8400 Coral Sea Street, Suite 1800, Mounds View MN 55112. If you need help changing the information on this database, please contact Ms. Marianne Bosley at marianne@atcb.com. Otherwise, you will have to submit a new application form with the correct address. Make sure the IC application form in this filing has the new address if the IC database is changed.

RESPONSE: Wallace has updated their company address in both FCC and IC websites and the FCC & IC applications have been corrected.

2. ATCB Comments: he confidentiality letter for this application has a different address than the address of record in the FCC and IC databases. This letter shows 8300 89th Avenue North, Brooklyn Park, MN as the company address. This letter also asks for confidential treatment of a block diagram and a parts list that have not been provided. In addition, the operational description that you want treated confidential reads more like a cover letter explaining the differences between the original device and the modified device. Please amend the confidentiality letter as noted to eliminate the block diagram and parts list. If you consider the submitted operational description confidential, leave it on the letter requesting confidentiality but supply a cover letter exhibit for the FCC and IC explaining the differences in the original and modified devices. The address on these letters must agree with the address of record for the FCC and IC.

RESPONSE: Revised.

3. ATCB Comments: The agent letter for this application has a different address than the address of record in the FCC and IC databases. This letter shows 8300 89th Avenue North, Brooklyn Park, MN as the company address. Either have the FCC and IC databases corrected as suggested in item 1 and 2 or provide a new agent letter with the correct address.

RESPONSE: Revised.

4. ATCB Comments: Please provide a completed Appendix A and B of RSS-102 in accordance with RSP-100, Issue 9 Section 5.4 dated June 2007.

RESPONSE: Done.

5. ATCB Comments: Please provide a completed Appendix 1 and 2 of RSP-100 in accordance with RSP-100. Issue 9 Section 5.4 dated June 2007.

RESPONSE: Done.

TÜV America Inc. 1775 Old Highway 8 NW Suite 104 New Brighton, MN 55112 Phone: (651) 631-2487 Fax: (651) 638-0285 E-mail: info@tuvam.com www.TUVamerica.com



The above referenced documents have been uploaded to the website at the same time as this response.

Please let us know if anything further is required.

Susan L Rupp

Susan L Rupp, Technical Writer TÜV America Inc Tel: 651 638 4585 / Fax: 651 638 0298 srupp@tuvam.com