
2. **Internal Photograph of EUT**

Model Name: H5V83Y

Report No.: EP780313-01




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UUU-4612

: 4 of 9 Page Number Report Issued Date : Oct. 05, 2017

Report Version : Rev. 01




Model Name: H5V83Y



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UUU-4612 Page Number : 5 of 9
Report Issued Date : Oct. 05, 2017
Report Version : Rev. 01






TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UUU-4612 Page Number : 6 of 9
Report Issued Date : Oct. 05, 2017
Report Version : Rev. 01




Model Name: H5V83Y



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UUU-4612 Page Number : 7 of 9
Report Issued Date : Oct. 05, 2017
Report Version : Rev. 01



Model Name: H5V83Y




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UUU-4612 Page Number : 8 of 9
Report Issued Date : Oct. 05, 2017

Report Version : Rev. 01







TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UUU-4612 Page Number : 9 of 9
Report Issued Date : Oct. 05, 2017

Report Version : Rev. 01