





Appendix B. Setup Photograph Spurious Conduction



Front View

Rear View

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : B1 of B3
Report Issued Date : Jul. 09, 2007
Report Version : Rev. 02








Side View

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : B2 of B3


Report Issued Date : Jul. 09, 2007

Report Version : Rev. 02





Spurious Radiation



Front View

Rear View

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : B3 of B3
Report Issued Date : Jul. 09, 2007
Report Version : Rev. 02