


Report No.: FA971421B

Appendix D. Product Photos



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UVZP37BW Page Number : D1 of D2
Report Issued Date : Oct. 14, 2009
Report Version : Rev. 01



Report No.: FA971421B

Antenna Location:



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UVZP37BW Page Number : D2 of D2
Report Issued Date : Oct. 14, 2009
Report Version : Rev. 01



Appendix E. Test Setup Photos



Face of the DUT with Phantom 1.5 cm Gap

Bottom of the DUT with Phantom 1.5 cm Gap

Report No.: FA971421B

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UVZP37BW Page Number : E1 of E1
Report Issued Date : Oct. 14, 2009
Report Version : Rev. 01