CETECOM ICT Services GmbH

Untertürkheimer Str. 6-10, 66117 Saarbruecken RSC-Laboratory


Phone: +49 (0) 681 598-0 Phone: +49 (0) 681 598-0 Fax: -9075 Fax: -9075



Test report no.: 2-4364-01-02/06 Date: 2006-07-26 Page 21 of 36

5 Annex B: Photographs of Test site

Photo 1 (Radiated Emissions): RSS P1



CETECOM ICT Services GmbH Untertürkheimer Str. 6-10, 66117 Saarbruecken Phone: +49 (


RSC-Laboratory

Phone: +49 (0) 681 598-0 Phone: +49 (0) 681 598-0 Fax: -9075 Fax: -9075



Test report no.: 2-4364-01-02/06 Page 22 of 36 Date: 2006-07-26

Photo 2 (Radiated Emissions):



CETECOM ICT Services GmbH Untertürkheimer Str. 6-10, 66117 Saarbruecken Phone: +49 (


RSC-Laboratory

Phone: +49 (0) 681 598-0 Phone: +49 (0) 681 598-0 Fax: -9075 Fax: -9075



Test report no.: 2-4364-01-02/06 Page 23 of 36 Date: 2006-07-26

Photo 3 (Radiated Emissions): RSS T2



CETECOM ICT Services GmbH Untertürkheimer Str. 6-10, 66117 Saarbruecken Phone: +49 (o

RSC-Laboratory

Phone: +49 (0) 681 598-0 Phone: +49 (0) 681 598-0 Fax: -9075 Fax: -9075



Test report no.: 2-4364-01-02/06 Page 24 of 36 Date: 2006-07-26

Photo 4 (Radiated Emissions):

