FCC ID : UWDA00044109 Test report No. : 27CE0032-HO Page : 11 of 25

Issued date : January 9, 2007

Conducted emission






UL Apex Co., Ltd. YAMAKITA EMC LAB.

907 Kawanishi, Yamakita-machi, Ashigarakami-gun, Kanagawa-ken, 258-0124 JAPAN

FCC ID : UWDA00044109 Test report No. : 27CE0032-HO Page : 12 of 25

Issued date : January 9, 2007


Radiated emission



(9kHz-30MHz)



(30-1000MHz)




UL Apex Co., Ltd. YAMAKITA EMC LAB.


907 Kawanishi, Yamakita-machi, Ashigarakami-gun, Kanagawa-ken, 258-0124 JAPAN


FCC ID : UWDA00044109 Test report No. : 27CE0032-HO Page : 13 of 25 Issued date : January 9, 2007

Pre-check of the worst position (IDS RFID module)

	IDS RFID module	Antenna
Measuring antenna: Horizontal	Z	Z
Measuring antenna: Vertical	Z	Z








UL Apex Co., Ltd. YAMAKITA EMC LAB.


907 Kawanishi, Yamakita-machi, Ashigarakami-gun, Kanagawa-ken, 258-0124 JAPAN


FCC ID : UWDA00044109 Test report No. : 27CE0032-HO Page : 14 of 25

Issued date : January 9, 2007

Pre-check of the worst position (Antenna)







UL Apex Co., Ltd. YAMAKITA EMC LAB.

907 Kawanishi, Yamakita-machi, Ashigarakami-gun, Kanagawa-ken, 258-0124 JAPAN